# Monitor Connections

- **Check what type of output the monitor has and make sure you have the correct cable and adapter.**
  - Display Port
  - VGA
  - DVI
  - HDMI

Dell Dock WD19TB Connections

Figure 1 (above) – Dell WD19 Dock

Figure 2 (above) – Dell WD19 Dock connections

This dock can connect up to three monitors via two native Displayport (5) and one HDMI (6) connector

- USB-C connector (Front dock)
- USB-3 Connector (Front Dock)
- Audio/Headset Jack (Front Dock)

- **For DisplayPort to DisplayPort connection.**

  - Connect the power supply to the docking station (10) *figure 2.*
  - The Dock has two DisplayPort connections at the back (5) *figure 2.*
  - Connect one end of the DisplayPort to the dock and the other end to the monitor.
  - If a second monitor is required connect the second DisplayPort socket (5) *figure 2* to dock and the other end to the monitor.

- **For DisplayPort to DVI Adapter**

  - Connect the power supply to the docking station (10) *figure 2.*
    a. If using a DisplayPort to DVI Adapter, make sure the DVI cable is connected to the adapter and tighten.
    b. Connect the other end of the DVI to the socket at the back of the monitor.
    c. For HDMI (6) *figure 2,* connect one end to the HDMI cable to the Dock and the other end to the monitor.


Figure 3 (above) – Dell WD19 Dock example connections